


INSTALLATION INSTRUCTIONS


ZEN URINAL DIVISION
















IMOPORTANT: Both the brackets must be fastened into sufficent framing.
































V 17/01/2024

Distributed by:

